

RHINESTONE TRANSFERS

www.heattransferwarehouse.com

888.819.4421









APPLICATION INSTRUCTIONS



Material
Cotton, Polyester, blends.
May work on other
surfaces. Please test.
**No Nylon



Cut or print Direction NA



Application Temperature 305 °F



Application Time

15 Seconds



Application PressureMedium to firm, even pressure



Peel Peel cold



Washing & Care
Wash with cold water,
best to hang dry

STEP-BY-STEP INSTRUCTIONS

PRESS & PEEL

- -Peel off backing
- -Load garment onto heat press
- -Place design right reading onto garment
- -Set heat press to 305 degrees F
- -Press with medium to firm, even pressure for 15 seconds
- -Peel cold in one smooth direction