

# QUICK REFERENCE GUIDE DIGITAL PRODUCTS

## MATERIALS PROPERTIES

- ✓ Proven application success
- T Test Prior to full run
- OK May be suitable, please test
- ✗ Will NOT apply to fabric

MATERIAL DESCRIPTION	Cotton	Polyester	Blends	Spandex	Lyra	Linen	Nylon	Nylon Mesh	Leather	TRANSFER TAPE REQUIRED	TEMPERATURE SETTINGS	APPLICATION TIME	APPLICATION PRESSURE	PEEL WARM/PEEL COLD	PRINT or CUT DIRECTION	WASHING & CARE	
<b>ColorPrint Solvent/Ecosol</b>	✓	✓	✓	✓	✓	✓	✓	✓	OK					Warm,			
<b>White &amp; Silver C-Silver2475 &amp; CS-2475</b>	Most Fabrics	✓	✓	✓	T	T	✓	✗	✗	✗	✓	325°-335°	15 Sec.	Hard	Almost hot	Right Reading	Turn Inside out, Cold Water, Tumble Low
<b>Clear Matte CPSC 4625M</b>	White/Light Materials	✓	✓	✓	T	T	✓	✗	✗	✗		330°-340°	17 Sec. 8 Sec.	Firm	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Clear Gloss CPSC 4626G</b>	White/Light Materials	OK	OK	OK	OK	OK	OK	✓	✓	✓		330°-340°	17 Sec. 8 Sec.	Firm	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Leather/Vinyl CPLV2700/CLV2475</b>	Heat-sensitive Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK	✓	170°-200°	15 Sec. Repress if required	Firm	Warm	Right Reading	Turn Inside out, Cold Water, Tumble Low
<b>ColorPrint™ II</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK	✓	300°-315°	30 Sec.	Hard	Cold	Right Reading	Warm Wash, Tumble Dry Normal
<b>Classic ColorPrint™</b>	Most Fabrics	✓	✓	✓	✓	✓	OK	✗	✗	✗	✓	300°	30 Sec.	Hard	Cold	Right Reading	Warm Wash, Tumble Dry Normal
<b>GlitterPrint™</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK	✓	300°-315°	30 Sec.	Hard	Cold	Right Reading	Warm Wash, Tumble Dry Normal
<b>HTW Clear Flex2 ColorPrint™</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK		302°	10 Sec.	Medium-Firm	Hot	Right Reading	Warm/Hot Wash, Tumble Dry Normal, Do NOT Iron
<b>HTW Clear Flex ColorPrint™</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK		275°	5 Sec.	Light-Medium	Hot & Repress	Right Reading	Turn Inside-Out, Cold Wash, Tumble Dry on Low
<b>HTW Metallic / Silver Chrome CP™</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK		300°	5 Sec.	Light-Medium	Hot & Repress	Right Reading	Turn Inside-Out, Cold Wash, Tumble Dry on Low

# QUICK REFERENCE GUIDE APPLICATION & USE GUIDE

## MATERIALS PROPERTIES

- ✓ Proven application success
- T Test Prior to full run
- OK May be suitable, please test
- ✗ Will NOT apply to fabric

MATERIAL DESCRIPTION	Cotton	Polyester	Blends	Spandex	Lyra	Linen	Nylon	Nylon Mesh	Leather	TRANSFER TAPE REQUIRED	TEMPERATURE SETTINGS	APPLICATION TIME	APPLICATION PRESSURE	PEEL WARM/PEEL COLD	PRINT or CUT DIRECTION	WASHING & CARE	
<b>Flex Plus</b>	✓	✓	✓	T	T	✓	✗	✗	✗		330°-335°	17-20 Sec.	Firm	Warm or Cold	Reverse	Warm Wash, Tumble Dry Normal	
<b>Nylon Flex</b>	Heat-sensitive Fabrics	✓	✓	✓	T	T	✓	✓	✓		225°-310°	5 Sec. 10-15 Sec.	Firm	Luke Warm	Reverse	Turn Inside out, Cold Water, Tumble Low	
<b>BLOCK Out</b>	Blocks dye migration on poly/poly-blends	OK	✓	✓	T	T	OK	✗	✗	✗		320°-330°	17-20 Sec.	Firm	Cold	Reverse	Warm Wash, Tumble Dry Normal
<b>HTWSport</b>	Most Fabrics	✓	✓	✓	T	T	✓	T	✓	✗		320°	10-12 Sec.	Medium	Warm or Cold	Reverse	Warm Wash, Tumble Dry Normal
<b>Poli-FLEX Image*</b>	Transfer Film with unique surface.	✓	✓	✓	✗	✗	T	T	✗	✗		330°-335° 305°-320°	17-20 Sec. 15-18 Sec.	Medium to Firm	Warm	Reverse	Warm Wash, Tumble Dry Normal
<b>Kwik Cut FLOCK</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗		320°-340°	10-15 Sec.	Firm	Cold	Reverse	Wash and Dry at Medium Temps.
<b>Metal FLEX</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗		310°-330°	17-20 Sec.	Firm	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low Low Brilliants - Hand Wash
<b>Metal FLAKE</b>	Most Fabrics	✓	✓	✓	T	T	✓	✗	✗	✗		305°-320°	15-18 Sec.	Medium to Firm	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Wild Fashion</b>	Most Fabrics	✓	✓	✓	T	T	✓	✗	✗	✗		325°-340°	12-15 Sec.	Hard to Firm	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Fashion Flex</b>	Most Fabrics	✓	✓	✓	T	T	✓	✗	✗	T		315°-330°	17-20 Sec.	Firm	Warm	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Reflect. Protect. Cotton 4781 &amp;</b>		✓	✓	✓	T	T	✓	✓	✓	T		295°-305°	17-20 Sec. 2 Sec.	Firm	Warm	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Reflect. Protect. Cotton 4782</b>		✓	✓	✓	T	T	✓	✓	✓	T		275°-305°	3-5 Sec. 5-7 Sec.	Medium	Cold	Reverse	Turn Inside out, Cold Water, Tumble Low
<b>Reflect. Protect. Nylon 4882</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK	✓	305°	5 Sec. & Repeat	Medium	Hot	Cut in Reverse	Warm Wash, Tumble Dry Normal
<b>ReflectAll™</b>	Most Fabrics	✓	✓	✓	OK	OK	OK	OK	OK	OK		305°	5 Sec. & Repeat	Medium	Hot	Cut in Reverse	Warm Wash, Tumble Dry Normal
<b>EasyWeed Electric™</b>		✓	✓	✓	✗	✗	✓	✗	✗	✗		311°	15 Sec.	Medium	Hot	Right Reading	Warm Wash, Tumble Dry Normal
<b>VideoFlex® Glitter™</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗	✓	311°	15 Sec.	Medium	Cold	Cut in Reverse	Warm Wash, Tumble Dry Normal
<b>FLOCK - Siser™</b>		✓	✓	✓	✗	✗	✓	✗	✗	✗		320°	15-20 Sec.	Medium	Cold	Cut in Reverse/Weed	Warm Wash, Tumble Dry Normal
<b>EasyWeed Glow In The Dark</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗		305°	10-15 Sec.	Medium	Warm	Cut in Reverse/Weed	Warm Wash, mild detergent, Tumble Dry Normal
<b>Stretch - Siser™</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗		305°	15 Sec.	Medium	Hot or Cold	Cut in Reverse/Weed	Warm Wash, mild detergent, Tumble Dry Normal
<b>3D Puff XPD - Siser™</b>	Most Fabrics	✓	✓	✓	✗	✗	✓	✗	✗	✗		330°	5 Sec. + 10 to 15 More	Medium	Hot	Cut in Reverse/Weed	Warm Wash, mild detergent, Tumble Dry Normal
<b>HTW Reflective Color</b>	Most Fabrics	✓	✓	✓	✓	✓	✓	✓	✓	✓		300°	5-10 Sec.	Medium	Warm	Cut in Reverse	Turn Inside out, Cold Water, Tumble Low

## QUICK REFERENCE GUIDE

HTW PRODUCT APPLICATION GUIDE

Use this Quick Reference Materials Guide when comparing all digital and non-digital Heat Transfer Warehouse Products for Specified Applications and Use.

We have put together this handy guide so that you can quickly compare our products, determine which product best suits your needs.

You can also reference this page and have an easy place to find all critical information for applying each product properly for the best results.

Thank you for using the Heat Transfer Warehouse, we look forward to working with you more in the future. If there are any products you are looking for that you do not see in this catalog, please contact us and we will see what we can do about adding your favorite items to our store.

## Ordering Information

### ONLINE ORDERING |

[www.heattransferwarehouse.com](http://www.heattransferwarehouse.com)

Online ordering can be done directly from our website 24 hours a day.

### PHONE ORDERING |

Toll Free & Local : 1-888-819-4421  
701-356-3160

### FAX ORDERS | Fax 1-701-356-3162

Make clear reference to product names, codes, quantity desired, and your specific company information. Indicate your company name, address, & contact numbers - it is also helpful to include the person's name placing the order in case we have questions.

### E-MAIL ORDERS |

[orders@heattransferwarehouse.com](mailto:orders@heattransferwarehouse.com)

©Copyright 2010 Heat Transfer Warehouse. All rights reserved.



The Heat Transfer Warehouse  
2201 12<sup>th</sup> St. N • Unit F • Fargo, ND 58102  
[www.heattransferwarehouse.com](http://www.heattransferwarehouse.com)